



Ideal Tint

Cleaning the Frame

Dust and dirt get stuck in frames and gaskets and can wash out during installation and end up trapped between the film and glass. It is important to clean frames thoroughly to reduce contamination. There are different techniques depending on the type of frame you are working on. Here are the basic steps for cleaning window frames:

1. Spray the window with soap and water mixture making sure to spray the frame.
2. Adjust the sprayer to "stream" and flush out the gasket starting at the top and working your way down and around the window.
3. Use your white scrub pad and gently scrub the frame and gasket around the entire window.
4. Adjust your sprayer back to "heavy mist" and rinse off the top and two sides of the frame.
5. Wipe off the frame starting at the top and working down each side with a paper towel to remove any particles of dirt.
6. Re-spray the window and lightly wet the gasket. With a clean paper towel, dry the frame and gasket. When the towel collects some dirt fold it over to a clean spot and continue wiping.

